
DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000665 Address: 333 Burma Road **Date Inspected:** 21-Oct-2007

City: Oakland, CA 94607

OSM Arrival Time: 1430 **Project Name:** SAS Superstructure **OSM Departure Time:** 2300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: N/A **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No **Delayed / Cancelled:** Yes N/A No

34-0006 **Bridge No: Component:** OBG - Shapes

Summary of Items Observed:

OBG-Structural Shapes


The Caltrans Quality Assurance (QA) Inspector Charlie Franco was present at the time requested by ZPMC QA Representative Eric Hu, to randomly verify sand blasting and coating operations of ASTM A709 GR50 W21 X 57 X 11,800 Structural Shapes (Beams). The QA Inspector randomly observed 18 each of the W21 X 57 X 11,800 Beams being shot blasted with 1.5 millimeter diameter steel shot and coated with a zinc protective coating. The QA Inspector observed the 18 Beams being run through 2 consecutive in line shot blasting apparatus, placed on horses and then spray coated. The QA Inspector randomly observed material information being recorded by ZPMC Quality Control personnel after placement on the shot blasting apparatus rollers, but prior to the actual shot blasting. The QA Inspector randomly observed the material information being transferred to the beams after the spray coating had been applied. The attached photographs provide additional detail.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)














WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

The QA Inspector asked Mr. Hu copies of the Material Test Reports for the W21 X 57 X 11,800 Beams and Material Data Sheets for the zinc coating. Mr. Hu informed the QA Inspector that he would supply the QA Inspector with the requested information tomorrow.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Franco, Charlie	Quality Assurance Inspector
Reviewed By:	Cochran,Jim	QA Reviewer